

Soil Classification & Assessment

Site:	New Road, Havant, PO6 3ES								
Compiled	C. Murrell, BSc (Hons), MSc, MIEnvSci Environmental Chemist	Signed	Flevel	Date	02/01/2018				

This assessment is based on the information sent to HWM Ltd, as specified by the report number, and the waste classification reflects our opinion only. The responsibility to ensure that the waste is imported to a suitably classified site lies with the waste producer

Part of HWM Group | Otterbourne Farm | Kiln Lane | Otterbourne | Hampshire | SO21 2EN T. 01962 718030. E. enquiries@hwmgroup.co.uk | www.hwmgroup.co.uk

Sample No.	Depth(m)	Soil Type (Lab)	Report No.	EWC code	Hazard codes	Asbestos	Concentrations in mg/kg. Metals reported as elemental concentration, but worse case compounds used to classify
BH01	0.40	Sandy clay	14-17407	17 05 03*	HP8, HP14	Not detected	pH: 11.7, Benzo(a)anthracene: 55
BH02	0.60	Sandy clay	14-17407	17 05 03*	HP7, HP11	No screen	TPH: 4700
BH03	0.40	Sandy Clay	14-17407	17 05 04	Non-Hazardous	No screen	
BH04	0.50	Sandy Clay	14-17407	17 05 03*	HP7, HP11, HP14	CH (LF) <0.001%	TPH: 3424, Lead:2178, zinc:3213